




The message "Purge Failed" or "Autozero Failed" is displayed

PROBLEM:

Before starting the refrigerant recycling phase, the **Konfort VAS 581 003** displays one of the following messages:



SOLUTION:

- Make sure that the **transparent glass** located on the side of the unit will be properly screwed in:



In case the problem would persist, contact your **TEXA Service Provider**.