



The Konfort VAS 581 003 displays the message “Int. Tank Pressure Too High”


PROBLEM:

During the refrigerant recycling phase, the **Konfort VAS 581 003** displays the following message:



SOLUTION:

- Select, from the **Additional Functions** menu, the option named **Non-Condensable Gas**:



WARNING: The procedure of check/discharge of the non-condensable gases from the internal vessel could require several minutes.

In case the problem would persist, contact your **TEXA Service Provider**.