



The Konfort VAS 581 003 does not power on

PROBLEM:

The **Konfort VAS 581 003** does not power on while pushing the main switch.

SOLUTION:

- Make sure that the unit will be connected to an adequate **network power supply (230V – 50Hz)**.
- Make sure that the **safety switch** located on the console of the unit has not be actioned. In case, restore the switch by rotating it clockwise:



In case the problem would persist, contact your **TEXA Service Provider**.